



Note: Mount suppressor as close as possible to coils. Only one suppressor is required on the power supply that feeds all four coils.

Mfr Part No. - Mitsubishi H6T10271A

Figure I15.1 - Nissan Vq30 Internal Ignitor Coil Wiring